

#	Refdes	UT_DEVICE	UT_VALUE	UT_PKGTYPE	REMARK
2	C2,C1	CAP_NPO	47p	0603	
2	C3,C4	CAP_Y5V	1u	0603	
1	C5	CAP_Y5V	4u7	0805	
4	C6...C9	CAP_Y5V	100n	0603	
8	D1...D8	DIO9900	BAV99	SOT23	
1	J1	HDR_5	53261_0590	532610590	
4	J2,J3,J5,J6	HDR_4	M22_2010405	HDR1X4_2MM	NOT PLACED
1	J4	HDR_4	52207_0417	522070417	
1	J7	HDR_3	M22_2010305	HDR2MM_1X3	NOT PLACED
2	R1,R3	RESISTOR	27E	0603	
1	R2	RESISTOR	1k5	0603	
4	R4...R6,R8	RESISTOR	15k	0603	
1	R7	RESISTOR	33k	0603	
2	R9,R10	RESISTOR	4k7	0603	
1	U1	TUSB3410	TUSB3410	VQFP32	
1	U2	ADS7846	ADS7846N	TSSOP16	
1	U3	TPS76333	TPS76633	SOT23_5	
1	U4	24LC128	24LC128SN	SO8	
1	VR1	VARISTOR	5V6 30A	0603	
1	X1	RESONATOR	PBRC_12.00BR	PBRC_BRN	